POM
Datasheet

Density

Melting point

Decomposition temperature

Recommended printing temperartue

Distortion temperature

Speed

Elongation

Tolerance

First layer temperature

Heatbed temperature

Pack dimensions

Pack weight

Melt index

Impact resistance



- The heatbed is required
- It requires the use of laquer on the printing surface
- Print in a well-ventilated room